

SECTION 5

PRESSURES

A handloader, especially one who's trying to get the best performance value from his labor, has a responsibility that permeates all aspects of metallic cartridge reloading: know what is being done *before* it is done. Anticipate. Pay attention. Experience confirmation of success more often than consequence of failure.

CONTENTS**5.1 Manual Interpretation**

- 234 Critic's Corner
- 236 Points of Contention
- 239 More On Manuals
- 240 Competitive Stress

5.2 Load Limits [pressure signs]

- 242 Borrowing Trouble
- 243 PSI-fi
- 244 Staying On Top Of It
- 246 Getting To The Bottom Of It
- 248 Piercings & Pops
- 250 Bullet Effects
- 251 Other Causes
- 253 Not Stressed, Just Tired
- 256 Undercooked
- 256 Living Under Pressure
- 258 Compensations
- 258 Knowledge is Knowledge

5.3 Case Neck Doughnuts

- 262 Deep Fried
- 264 Sugar Coated